

Color Checking Test Chart Image

Article Number: 31 | Rating: 4.7/5 from 3 votes | Last Updated: Sun, Apr 17, 2011 7:31 AM

The PDI-Target DCP Hi-Res is a great way to test colors after ensuring priming of the printer. This attachment is the final step in assuring you are capable of producing photo quality output. The process is simple; 1) Nozzle check patterns (from printer software utility "maintenance page/tab") 2) Stress testing by utilizing our Purge Color bar charts per the How To Test pdf document or video 3) Color management placed back to "ON", just hit the reset defaults from within your printer software and print the PDI-Target. This attachment is suitable dpi for testing full page 8.5x11 prints. Ensure (if opening with Photoshop or other photo software) that you are applying no color management when opening the image (for best results).



Posted : [Ross Hardie](#) - Mon, Feb 22, 2010 3:12 PM. This article has been viewed 45911 times.

Online URL: <https://www.inkjetcart.com/support/article/color-checking-test-chart-image-31.html>

