

Canon ipf cartridge collar removal PFI-101 PFI-102 PFI-103

Posted: **Ross Hardie** [ross@inkjetcarts.us]

Online URL:

<http://www.inkjetcarts.us/support/article/canon-ipf-cartridge-collar-removal-pfi-101-pfi-102-pfi-103.html>

Professional removal of Canon cartridge collars requires special tools.

Knowing how to do it properly with good instructions is 95% of the battle.

The proper tools can be substituted with onsite materials you can use as alternatives once you have a good understanding on how the proper tools are used.

See the attached document for the following items;

-

How to remove the bottom collar from Canon ipf imagepregraf PFI-101 PFI-102 or PFI-103 inkjet ink cartridges

-

How to replace the chip(s) on the above cartridges in case you need our compatible chips

-

How to reassemble the collar properly to a Canon cartridge or to a refillable cartridge

In the Case of moving the factory OEM chip AND collar to our refillable you only need to ensure

-

Correct orientation / facing of the chip Glance at a factory original cart while replacing your chip/collar

-

Correct security of the collar to the refillable cartridge (Use a strong tape and attach securely)

InkJetCarts

<http://www.inkjetcarts.us/>